

NOTICE DE MONTAGE
INSTRUCTIONS FOR ASSEMBLY
MONTAGEANLEITUNG
GEBRUIKSAANWIJZING
ISTRUZIONI DI MONTAGGIO
INSTRUCCIONES DE MONTAJE
INSTRUCOES DE MONTAGEM

buronomic
FABRICANT FRANÇAIS

N° DV40794

CONCEPTION ET REALISATION BUREAU D'ETUDES BURONOMIC

GARANTIE (Vices cachés)
_ Référence produit à nous communiquer impérativement en cas de litige :
Voir étiquette apposée au dos du produit

GARANTEE (defect)
_ In the event of complaint, it is essential to mention the product reference :
See label affixed to the back of the product.






GARANTIE (fabrika bezbednost)
_ Im streifnisi sit uns die produktreferenz mitzuteilen :
Siehe etikett auf produkttrucksseite.

WAARBORG (de verborgen gebreken)
_ Vermeld in geval van klachten altijd het productnummer :
Zie label op de achterzijde van het product



GARANZIA (vici occulti)
_ Specificare obbligatoriamente il riferimento prodotto in caso di contestazioni :
Si veda l'etichetta applicata dietro il prodotto

GARANTIA (defectos ocultos)
_ Referencia de producto citese obligatoriamente en caso de reclamacion :
Ver etiqueta en la parte posterior del producto.

GARANTIA (vicio oculto)
_ Em caso de reclamacao indiqu-nos imperativamente a referencia do produto :
Ver etiqueta fixada na parte posterior do produto



AIDE
HELP
HILFE
HULP
AYUDA
AJUDA
AIUTO



NOMENCLATURE (Paris list)
(Stückliste)
(Onderdelenlijst)
(Nomenclatura)
(Lista de peças)


QUINCAILLERIE (Hardware)
(Beschläge)
(Ijzerwaren)
(Ferreteria)
(Herrajes)
(Quinquilharia)

Rep.	Pièce	Qté	A	B	C
A	VIS TCHC M6x16	4/8			
B	Clé 6 pans 5mm	1			
			D	E	F
			G	H	I
			J	K	L
			M	N	O
			P	Q	R


NOTICE D'ASSEMBLAGE

LISTE DES PIÈCES ET OUTILS


NO	NOM	QTE	NO	NOM	QTE
1	COLONNES	1set	11	VIS M6*12	8
2	PATIN	4	12	BUTÉE DE PROTECTION	6
3	PIÈTEMENT	2	13	VIS ST3.5*19	2
4	VIS M8*16	8	14	VIS ST4.8*19	8
5	ATTACHE	2	15	BOÎTIER DE CONTRÔLE	1
6	VIS M6*14	8	16	BLOC ALIMENTATION	1
7	VIS M6*10	8			
8	TRAVERSE	1			
9	CLÉ 4MM	1			
10	CLÉ 5MM	1			




1 DESERRER LES 4 VIS DE LA TRAVERSE EN UTILISANT LA CLÉ SIX PANS 4MM PUIS AJUSTER LA EN FONCTION DU PLATEAU




2 ATTACHER LES COLONNES À LA TRAVERSE À L'AIDE DE 8 VIS M6*14 ET 4 VIS M6*12




3 ATTACHER LES PIÈTEMENTS AUX COLONNES EN UTILISANT LES VIS M8*16 PUIS FIXER MANUELLEMENT LES PATINS




4 FIXER LES ATTACHES À LA TRAVERSE AVEC LES VIS M6*12 PUIS FIXER LES BUTÉES DE PROTECTION AUX ATTACHES ET À LA TRAVERSE




5 AJUSTER LA LARGEUR DU CADRE DU BUREAU EN FONCTION DU PLATEAU PUIS FIXER LE AVEC LES VIS M6*12. (IL EST RECOMMANDÉ DE LAISSER 5 À 8 CM MINIMUM ENTRE LE CÔTÉ DU PLATEAU ET LE CADRE.)



6 MONTER LE BOÎTIER DE CONTRÔLE SOUS LE PLATEAU À L'AIDE DES VIS AUTOTARAUDEUSES ST4.8 PUIS MONTER LE TERMINAL SOUS LE PLATEAU À L'AIDE DES VIS AUTOTARAUDEUSES ST3.5





7 CONNECTER LES COLONNES ET LE BOÎTIER DE CONTRÔLE AU BLOC ALIMENTATION. CONNECTER LE CÂBLE D'ALIMENTATION AU BLOC D'ALIMENTATION. VOUS POUVEZ MAINTENANT CONNECTER LE CÂBLE D'ALIMENTATION AU SECTEUR




Assembly Instructions

Parts and Tools list


NO.	Name	Qty	NO.	Name	Qty
1	Legs	4	12	M6*20 Screw	8
2	Brackets	4	13	ST4.8*19 Screw	24
3	Beam	2	14	ST3.5*19 Screw	4
4	Cable Tray	1	15	M6*12 Screw	16
5	Screen Stand	4	16	Rubber Cushion	20
6	Connection Beam	2	17	M6*16 Screw	8
7	4mm Hex Spanner	2			
8	5mm Hex Spanner	2			
9	M8*10 Screw	8			
10	Gasket8	8			
11	M6*14 Screw	16			




- 1 Loosen the 8 screws of beam using 4MM hex spanner, adjust the beam to proper position to fit the desktop we recommend leaving 15CM of the desktop width (on each end) and then tighten screws




- 2 Attach legs to the beam using 8 of M6*14 screws and 4 of M6*12 screws, the other side is same



- 3 Attach connection beam to leg using 8 of M8*10 screws and 8 of gasket8.




- 4 Open the cover of cable tray, using 4mm Hex spanner to loosen the screws on both sides of cable tray, and then adjust the cable tray's length.




Assembly Instructions


- 5** Overturn frame, and fixed the cable tray, then attach screen stand to connecting beam using 5mm Hex Spanner and 8 of M6*20 screws and close the lid of cable tray.




- 6** Attach connection brackets to beam using 8 of M6*12 screws and then fit the rubber cushions to the brackets and beams.



- 7** Fix table top to frames with 12 of ST4.8 screws, then fix control boxes to below table top with 4 of ST4.8 screws, at last fix handsets to below table top with 4 of ST3.5 screws (you can use the self tapping screw or in case of inserts use the M6*16 screw).



- 8** Connect the control box to the handset and to the motor



Operation Guide

1. System Initialization

When we complete the installation of the desk frame, we need to reset the system, to make the system be initialized.

Resetting procedure is as follows, press and hold on both "↑" and "↓" button together until the lifting column be lowest and you will hear a beep, and the display shows the number for the lowest height, then whole steps finishes.

If the system doesn't work normally when we use it, we need to repeat the above procedure.

2. Normal Operation

Drive the desk to the desired height when pressing and holding "↑" or "↓" button.

3. Setting the memory function

When the desk rises to the height which you want to memorize, please press and hold the "M" button till the display flashes and then press "1" button. Position 1 is now memorized. Repeat the above procedure for positions 2, 3 & 4. These four number buttons can memorize four different heights repeatedly. And those data won't be lost in case power is off.


4. The function of metric-inch conversion

The function base on the premise that original keys function unchangeable, procedure as follows:

1. Press the "1" "2" "M" buttons together for about 5s, display "C-E" (flashing)---then continue to procedure 2,3.
2. Press button "1" within 5s, display "C", then switch to metric system CM---go into the general operation
3. Press button "2" within 5s, display "E" then switch to British system Inch---- go into the general operation
4. If above procedures no further operate over 5s, then will recover to the previous setting.

Notice

- 1: This product must meet the actual technical parameters in use.
- 2: The system should be away from water and corrosion resistant gas.
- 3: Please contact us or our distributors if there is anything wrong with the product.



NOTICE DE MONTAGE
INSTRUCTIONS FOR ASSEMBLY
MONTAGEANLEITUNG
GEBRUIKSAANWIJZING
ISTRUZIONI DI MONTAGGIO
INSTRUCCIONES DE MONTAJE
INSTRUCCOES DE MONTAGEM

buronomic
FABRICANT FRANÇAIS

N° DV40795

CONCEPTION ET REALISATION BUREAU D'ETUDES BURONOMIC

GARANTIE (vices cachés)
_ Référence produit à nous communiquer impérativement en cas de litige :
Voir étiquette apposée au dos du produit

GARANTEE (defekt)
_ In the event of complaint, it is essential to mention the product reference :
See label affixed to the back of the product.


GARANTIE (fabrikationfelher)
_ Im streitfall sit uns die produktreferenz mitzuteilen :
Siehe etikett auf produktruckseite.

WAARBORG (de verborgen gebreken)
_ Vermeld in geval van klachten altijd het productnummer :
Zie label op de achterzijde van het product

GARANZIA (vizi occulti)
_ Specificare obbligatoriamente il riferimento prodotto in caso di contestazioni :
Si veda l'etichetta applicata dietro il prodotto

GARANTIA (defectos ocultos)
_ Referencia de producto citese obligatoriamente en caso de reclamacion :
Ver etiqueta en la parte posterior del producto.

GARANTIA (vicios ocultos)
_ Em caso de reclamacao indiqu-nos imperativamente a referencia do produto :
Ver etiqueta fixada na parte posterior do produto



ALCOOL A BRUIER
ANTHYLATED SPIRITS
BRENNSPIRITUS
BRANDSPIRITUS
ETANALO
ALCOHOL DE QUEMAR
ALCOOL ETIRICO


CHIFFON DOUX
SOFT RAG
LAPPEN
ZACHTE DOEK
FANNO MORCIDO
FANNO SUAVE
FANNO MAGIO

SAVON
SOAP
SEIFE
ZEEF
SAPONE
JABON
SABAO

CIRE
WAX
WACHS
WAS
CERA

AIDE

HELP
HILFE
HULP
AYUDA
AJUDA
AIUTO





NOMENCLATURE (Parts list)
(Stückliste)
(Onderdelenlijst)
(Nomenclatura)
(Lista de peças)

Rep.	Pièce	Qté
1	ECRAN AGGLO 160	1



QUINCAILLERIE (Hardware)
(Beschläge)
(Ijzerwaren)
(Ferramenta)
(Herrajes)
(Quinquilharia)

Rep.	Pièce	Qté	A	B	C
A	Vis TRL M6x40	4			
B	Ecrou borgne M6	4			
C	RONDELLE L8	4			
D	Cache Ø8	8			
E	Clé 6 pans 4mm	1			
			J	K	L
			M	N	O
			P	Q	R



1/A



1/B



2/A



2/B

